

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

| | |
|---|---|
| <u>DORM C</u> | Toaster present in Room, heater not functioning |
| => Room 6: Heater not functioning | |
| => Room 12: No Smoke Alarm. | |
| => Room 13: No Smoke Alarm. | |
| <u>Dorm D</u> | |
| => Room 7: Heater not functioning | |
| <u>Dorm E</u> | |
| => Room 15: Heater not functioning | |
| => Room 11: No electric outlet. | |
| <u>BANE 12</u> | |
| <u>Men's Room D</u> | |
| => electric outlet does not function | |
| <u>Dorm F</u> | |
| => Room 13: Heater Does not Function. | |
| => Room 3: Heater not functioning | |
| => Room 29: Heater not functioning | |
| => Room 26: Heater not functioning | |
| => Room 22: Heater not functioning | |
| => Room 22: electric outlet not functioning. | |
| <u>Dorm H</u> | |
| => Room 6: Heater and Smoke Alarm not functioning | |
| => Room 10: No Smoke Alarm | |
| => Room 20: Holes in Ceiling, | |

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Dorm C:

Ladies restroom: ok

Rm #3: ok

Rm #8: ok

Rm #10:

• Non-functioning heating unit

Rm #15: ok

Dorm D:

Rm #8: Non functioning heating unit

Rm #10: ok

Rm #2: • smoke alarm removed

Rm #4: • heater not used

Dorm E:

Room #5: ok

Room #16: heat not functioning

Room #12: • unauthorized cooking
• apparatus
• heat not functioning

Ladies lounge: ok

Dorm F:

Rm #14: • heat not functioning

Rm #10: • needs smoke alarm
• heat not functioning

Rm #5:

• Missing smoke alarm
• Heat not functioning
~~Recessed~~

Rm #28: • Heat not functioning
Rm #27 • Heat not functioning

Rm #24: ok

Rm #21: ok

Dorm H:

Rm #3: ok

Rm #5: .. unsanitary cond. on ceiling
• heat not functioning

Rm #15: ok

Rm #18: ok

Rm #19: ok

Rm #22: ok

Dorm G:

Rm #18: • no heating unit
present
• detached smoke alarm

Rm #18: ok

Dorm I:

Rm #4: ok

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Bldg. C:

Ladies bathroom - all ok
Unit #3 - 11ft x 12.3ft x
7ft (height)
~~20in. x 28in.~~
window

Bldg. D:

Unit #9 - inoperable heater
Unit #1 - inoperable heater

Bldg. E:

Unit #2 - no smoke alarm
Unit #18 - inoperable heater

Bldg. F:

Unit #15 - inoperable heater
Unit #32 - inoperable heater
Unit #25 - no smoke alarm
Unit #18 - no smoke alarm

Bldg. H:

Unit #9 - inoperable heater
Unit #14 - no smoke alarm

Bldg I:

Unit #5 - 9ft. 10in x
11ft 3in.
8ft. (height)
45in x 55in
(window)

- Ladies Lounge - all ok
- Kitchen/Restaurant - all ok
- common area - all ok

MULTIPLE DWELLING INSPECTION REPORT

SEQUENCE #: 00974

Page ____ of ____

Dorm C:

Unit # 6

- Heater non-functional

Unit # 11

- COOKING equipment

Dorm D:

Unit # 11

- Heater non-functional

Unit # 12

- Heater non-functional

Dorm E:

Unit # 9

- unsanitary conditions

Dorm F:

Unit # 1

- non-functional smoke alarm

Unit # 11

- non-functional Heater

Unit # 30

- COOKING equipment

Unit # 23

- NO smoke alarm

Dorm H:

Unit # 2

- NO smoke alarm

Unit # 7

- CRACKING / damage along front ceiling

Unit # 12

- Heater non-functional

- COOKING equipment

Dorm G:

Unit # 1

- NO smoke alarm

- Heater non-functional

Unit # 3

- NO batteries in smoke alarm

- Heater non-functional

Dorm G Room # 18:

Damaged smoke alarm



Missing heating unit



Dorm E: # 12 Unauthorized cooking apparatus



Dorm H: #5

Water damage to ceiling



Seq# 00974

3600 Laurel Ft Meade RD

Dorm
H
Room
20



Dorm
H
Room
20 .



Dorm
F
Room
22






Dorm H: Unit 12 – Cooking Equipment (Toaster)



Dorm H: Unit #7 – Crack/Damage along front ceiling



Dorm F: Unit #30 – Cooking Equipment (Microwave)



Dorm E: Unit #9 – Unsanitary Conditions



Dorm C: Unit #11 – Cooking Equipment (Slow Cooker)